



Overview: Part of spill impact on 4" Yokri Well 27 T Flowline at Yokri . Picture was taken during Joint Investigation on 3rd November 2020.



Close-up: Pin hole at 7 o'clock position on 4" Yokri Well 27 T Flowline at Yokri . Picture was taken during Joint Investigation on 3rd November 2020.