



Overview: Part of spill impact on 3inch Nun River Well 11 Lima Flowline at Oporoma. Picture was taken during Joint Investigation on 13th November 2020.



Close-up: Rough edge hole (Hidding behind the flange) at 6 o'clock position on 3inch Nun River Well 11 Lima Flowline at Oporoma. Picture was taken during Joint Investigation on 13th November 2020.