



11/16/2020 12:55:46 PM (+1.0 hrs) Lat=5.53529 Lon=5.19369 Alt=3ft MSL WGS-84

Overview: Part of spill impact on 6inch Escravos Well 13s Flowline at Ogidegben
Picture was taken during Joint Investigation on 16th November 2020.



11/16/2020 2:26:29 PM (+1.0 hrs) Lat=5.53536 Lon=5.1936 Alt=10ft MSL WGS-84

Close-up: Tear at 3 o'clock position on 6inch Escravos Well 13s Flowline at Ogidegben.
Picture was taken during Joint Investigation on 16th November 2020.