




Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline at Ejamah. Picture was taken during Joint Investigation on 4th September 2020.



Close-up: Plugged crude oil theft point installed at 12 o'clock position on 28" Nkpoku - Bomu Pipeline at Ejamah . Picture was taken during Joint Investigation on 4th September 2020.