



Overview: Part of spill impact on 8" Agbada 2 Nkpoku DeliveryLine at Omuohia - Igwuruta. Picture was taken during Joint Investigation on 9th September 2020.



Close-up: Plugged rough edge tear at 9 o'clock position on 8" Agbada 2 Nkpoku DeliveryLine at Omuohia - Igwuruta. Picture was taken during Joint Investigation on 10th September 2020.