



Overview: Part of spill impact on Otamiri Well 7S Flowline at Umuechem
Picture was taken during Joint Investigation on 11th September 2020.



Close-up: Hacksaw cuts of 1.2m apart all at 11 o'clock position on Otamiri Well 7S Flowline at Umuechem. Picture was taken during Joint Investigation on 11th September 2020.