




Overview: Part of spill impact on 16" Egbema - Assa Pipeline at Ekpeaga. Picture was taken during Joint Investigation on 28th September 2020.



Close-up: 2 nos crude oil theft points installed at 12 o'clock position on 16" Egbema Assa Pipeline at Ekpeaga. Picture was taken during Joint Investigation on 28th September 2020.