



Overview: Part of spill impact on 36inch Rumuekpe Nkpoku Pipeline at Adanta-lsiokpo .  
Picture was taken during Joint Investigation of 20<sup>th</sup> April 2021 .



Close-up: 4inch ball valve installed at 12 o'clock position on 36inch Rumuekpe Nkpoku Pipeline at Adanta-lsiokpo .  
Picture was taken during Joint Investigation of 20<sup>th</sup> April 2021 .