



Overview: Part of spill impact on 20" Kolocreek Rumuekpe Pipeline at Okoma 1.
 Picture was taken during Joint Investigation of 19th August 2021.



Close-up: 2inch ball valve and 2inch pipe installed at 12 o'clock position on 20" Kolocreek Rumuekpe Pipeline at Okoma 1.
 Picture was taken during Joint Investigation of 19th August 2021.