



Overview: Part of spill impact on 18" Kolocreek Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 27th August 2021.



Close-up: Plugged 20mm diameter smooth round edge hole at 12 o'clock position on 18" Kolocreek Rumuekpe Pipeline at Rumuekpe. Picture was taken during Joint Investigation of 27th August 2021.