



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Akara-Olu. Picture was taken during Joint Investigation of 29th August 2021.



Close-up: 60mm diameter inward dent at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Akara-Olu. Picture was taken during Joint Investigation of 29th August 2021.