



**Overview:** Part of spill impact on Forcados Single Point Mooring 2 at Ogulagha.  
 Picture was taken during Joint Investigation of 16<sup>th</sup> August 2021.

Below picture shows the Nipple of interest on SBM2.  
 PDU Assembly drawing is as attached, Item #06 is the point of leak.  
 See the note section for description.



3/4" NPT SPECIAL PLUG (5mm dia. Hole)

**Close-up :** Failed special plug nipple on Forcados Single Point Mooring 2 at Ogulagha.  
 Picture was taken during Joint Investigation of 16<sup>th</sup> August 2021.