



Overview: Part of spill impact on 12" Imo River Ogale Pipeline at Ogale.  
 Picture was taken during Joint Investigation of 3<sup>rd</sup> September 2021.



Close-up: 1 inch nipple installed at 12 o'clock position on 12" Imo River Ogale Pipeline at Ogale.  
 Picture was taken during Joint Investigation of 3<sup>rd</sup> September 2021.