



Overview: Part of spill impact on 6" Imo River Well 59T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation on 15th December 2021.



Close-up: 2" Nipple installed at 3 o'clock position on 6" Imo River Well 59T Flowline at Igiriukwu-Owaza. Picture was taken during Joint Investigation on 15th December 2021.