



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation of 1st January 2022.



Close-up: Plugged 2inch weld neck flange installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation of 1st January 2022.