



Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 31st December 2021.



Close-up: 3inch ball valve with 3inch elbow connection installed at 12 o'clock position on 20" Kolocreek - Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 31st December 2021.