



Overview: Part of spill impact on Forcados Terminal Skimming Pit at Ogulagha. Picture was taken during Joint Investigation of 23rd December 2021.



Close-up: Failed Skimming Pit on Forcados Terminal Skimming Pit at Ogulagha. Picture was taken during Joint Investigation of 23rd December 2021.