



Overview: Part of spill impact on 8inch Ubie Deliveryline at Idu-Ekpeye. Picture was taken during Joint Investigation of 11<sup>th</sup> February 2021.



Close-up: Pin hole at 5:30 o'clock position on 8inch Ubie Deliveryline at Idu-Ekpeye. Picture was taken during Joint Investigation of 11<sup>th</sup> February 2021.