



Overview: Part of spill impact on 18inch Assa Rumuekpe Pipeline at Awara . Picture was taken during Joint Investigation of 14th February 2021.



Close-up: Plugged 2 nos of 2inch ball valves installed at 12 o'clock position on 18inch Assa Rumuekpe Pipeline at Awara . Picture was taken during Joint Investigation of 14th February 2021.