



Overview: Part of spill impact on 20inch Kolocreek – Rumuekpe Pipeline at Odau Km9 .  
Picture was taken during Joint Investigation of 15<sup>th</sup> February 2021.



Close-up: 4inch valve with a concrete cast and a non-leaking 4inch valve of 5.2m apart installed at 12 o'clock position on 20inch Kolocreek – Rumuekpe Pipeline at Odau Km9 .  
Picture was taken during Joint Investigation of 15<sup>th</sup> February 2021.