




Overview: Part of spill impact on 14inch Okordia Rumuekpe Pipeline at Akinima . Picture was taken during Joint Investigation of 18th February 2021.



Close-up: Hacksaw cut at 2 o'clock position on 14inch Okordia Rumuekpe Pipeline at Akinima . Picture was taken during Joint Investigation of 18th February 2021.