



Overview: Part of spill impact on Bonny terminal single point mooring 3 (SPM3) at Bonny .
 Picture was taken during Joint Investigation of 6th February 2021.



Close-up: Ruptured hose on Bonny terminal single point mooring 3 (SPM3) at Bonny .
 Picture was taken during Joint Investigation of 24th February 2021.