



Overview: Part of spill impact on 14inch Okordia Rumuekpe Pipeline at Ikarama .
Picture was taken during Joint Investigation of 19th Feb 2021.



Close-up 1: A Tear at Point 1 (6 o'clock position) on 14inch Okordia Rumuekpe Pipeline at Ikarama . Picture was taken during Joint Investigation of 19th Feb 2021.



Close-up 2: Inward dent/double cut at point 2 (12 o'clock position) on 14inch Okordia Rumuekpe Pipeline at Ikarama . Picture was taken during Joint Investigation of 19th Feb 2021 .



Close-up 3: Chisel impact with no cut through at point 3 (12 o'clock position) on 14inch Okordia Rumuekpe Pipeline at Ikarama . Picture was taken during Joint Investigation of 19th Feb 2021 .