



Overview: Part of spill impact on Belema well 6 Wellhead at Belema.  
 Picture was taken during Joint Investigation of 11<sup>th</sup> March 2021.



Close-up: Vandalized wellhead on Belema well 6 Wellhead at Belema.  
 Picture was taken during Joint Investigation of 11<sup>th</sup> March 2021.