


Overview: Part of spill impact on 8" Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation on 4th January 2021.



Close-up: 1 inch nipple buried inside a concrete cast at 12 o'clock position on 8" Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation on 4th January 2021.