



Overview: Part of spill impact on 16inch Egbema Assa Pipeline at Obile. Picture was taken during Joint Investigation of 8th January 2021.



Close-up: 2.5inch ball valve with 2inch pipe connection installed at 12 o'clock position on 16inch Egbema Assa Pipeline at Obile. Picture was taken during Joint Investigation of 8th January 2021.