



Overview: Part of spill impact on 18inch Assa Rumuekpe Pipeline at Ububo Ochia. Picture was taken during Joint Investigation of 9th January 2021.



Close-up: 3inch ball valve installed at 12 o'clock position on 18inch Assa Rumuekpe Pipeline at Ububo Ochia. Picture was taken during Joint Investigation of 9th January 2021.