



**Overview:** Part of spill impact on 18inch Assa Rumuekpe Pipeline at Elele-Alimini. Picture was taken during Joint Investigation of 10<sup>th</sup> January 2021.



**Close-up:** Plugged crude oil theft point installed at 12 o'clock position on 18inch Assa Rumuekpe Pipeline at Elele-Alimini. Picture was taken during Joint Investigation of 10<sup>th</sup> January 2021.