



Overview: Part of spill impact on 14inch Okordia Rumuekpe Trunkline at Ukpeliède. Picture was taken during Joint Investigation of 25th January 2021.



Close-up: Plugged 3inch nipple installed at 12 o'clock position on 14inch Okordia Rumuekpe Trunkline at Ukpeliède. Picture was taken during Joint Investigation of 25th January 2021.