



Overview: Part of spill impact on 28inch Bomu Bonny Pipeline at Freetown. Picture was taken during Joint Investigation of 18th January 2021.



Close-up: 4inch crude oil theft valve installed at 12 o'clock position on 28inch Bomu Bonny Pipeline at Freetown . Picture was taken during Joint Investigation of 18th January 2021.