



Overview: Part of spill impact on 4inch ImoRiver 2-1-testline at Igiriukwu . Picture was taken during Joint Investigation of 30th January 2021.



Close-up: Hacksaw cut from 10 - 7 o'clock position and 10 - 8 o'clock position respectively on 4inch ImoRiver 2-1-testline at Igiriukwu . Picture was taken during Joint Investigation of 30th January 2021.