



Overview: Part of spill impact on 6inch kanbo well 6T flowline at Tunu . Picture was taken during Joint Investigation of 27<sup>th</sup> January 2021 .



Close-up: Pin hole at 3 o'clock position on 6inch kanbo well 6T flowline at Tunu . Picture was taken during Joint Investigation of 27<sup>th</sup> January 2021 .