



Overview: Part of spill impact on 18inch Egbema Assa Pipeline at Egbeda.
Picture was taken during Joint Investigation of 7th June 2021.



Close-up: 2inch ball valve installed at 12 o'clock position on 18inch Egbema Assa Pipeline at Egbeda.
Picture was taken during Joint Investigation of 7th June 2021.