



Overview: Part of spill impact on 20inch Kolocreek Rumuekpe Pipeline at Okporowo. Picture was taken during Joint Investigation of 11th June 2021.



Close-up: 4inch valve installed at 12 o'clock position on 20inch Kolocreek Rumuekpe Pipeline at Okporowo. Picture was taken during Joint Investigation of 11th June 2021..