



Overview: Part of spill impact on 24inch Trans Escravos Pipeline at Obotobo. Picture was taken during Joint Investigation of 10th June 2021.



Close-up: Weld on 4inch valve installed at 12 o'clock position on 24inch Trans Escravos Pipeline at Obotobo. Picture was taken during Joint Investigation of 10th June 2021.