



Overview: Part of spill impact on 20inch Kolocreek – Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 19th June 2021.



Close-up: 4inch illegal connection installed at 12 o'clock position on 20inch Kolocreek – Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 19th June 2021.