



Overview: Part of spill impact on 12inch Imo River 1 – Ogale Pipeline at Owaza. Picture was taken during Joint Investigation of 24th June 2021.



Close-up: 2 nos 2inch ball valves of 1m apart installed at 12 o'clock position on 12inch Imo River 1 – Ogale Pipeline at Owaza. Picture was taken during Joint Investigation of 24th June 2021.