



Overview: Part of spill impact on 16inch Nun-River to Kolocreek Pipeline at Otuegwe Picture was taken during Joint Investigation of 29<sup>th</sup> June 2021.



Close-up: Hacksaw cut (2cm length) at 1 o'clock position on 16inch Nun-River to Kolocreek Pipeline at Otuegwe Picture was taken during Joint Investigation of 29<sup>th</sup> June 2021.