



Overview: Part of spill impact on 36inch Rumuekpe Nkpoku Pipeline at Ibaa.  
Picture was taken during Joint Investigation of 19<sup>th</sup> June 2021.



Close-up: 4nos crude oil theft points at 12 o'clock position on 36inch Rumuekpe Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 19<sup>th</sup> June 2021.