



Overview: Part of spill impact on 14inch Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 13th March 2021.



Close-up: 2inch nipple installed at 12 o'clock position on 14inch Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 13th March 2021.