



Overview: Part of spill impact on 8inch Isimiri Imo gate Pipeline at Umuelechi  
Picture was taken during Joint Investigation of 13<sup>th</sup> March 2021.



Close-up: Plugged inward dent and sharp edge hole between 10 to 12 o'clock position on 8inch  
Isimiri Imo gate Pipeline at Umuelechi. Picture was taken during Joint Investigation of 14<sup>th</sup> March  
2021.