



Overview: Part of spill impact on 4inch (Bulkline) Well 4 Flowline at Biseni.  
Picture was taken during Joint Investigation of 22<sup>nd</sup> March 2021.



Close-up: SP 1: Hacksaw cut from 10-12 o'clock position on 4inch (Bulkline) well 4 Flowline at Biseni. Picture was taken during Joint Investigation of 22<sup>nd</sup> March 2021.



Closeup: SP 2 Hacksaw cut from 9-11 o'clock position on 4inch (Bulkline) well 4 Flowline at Biseni. Picture was taken during Joint Investigation of 22<sup>nd</sup> March 2021.