



Overview: Part of spill impact on 28inch Bomu Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 18th March 2021.



Close-up: Crude oil theft point installed at 12 o'clock position on 28inch Bomu Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 18th March 2021.