



Overview: Part of spill impact on 6inch Seibuo Well 3 and 4 bulkline at Ogbeinbiri. Picture was taken during Joint Investigation of 15th March 2021.



Close-up: SP 1 : 2nos hacksaw cut at 3 and 9 o'clock position on 6inch Seibuo Well 3 and 4 bulkline at Ogbeinbiri. Picture was taken during Joint Investigation of 15th March 2021.



Closeup: SP 2: : 2nos hacksaw cut at 3 and 9 o'clock position on 6inch Seibuo Well 3 and 4 bulkline at Ogbeinbiri. Picture was taken during Joint Investigation of 15th March 2021.