



Overview: Part of spill impact on 18inch Assa - Rumuekpe Pipeline at Elele Alimini. Picture was taken during Joint Investigation of 1st April 2021.



Close-up: 2 nos of crude oil theft installed at 12 o'clock position on 18inch Assa - Rumuekpe Pipeline at Elele Alimini. Picture was taken during Joint Investigation of 1st April 2021.