



Overview: Part of spill impact on 8inch Afam Well 27T Flowline at Egberu  
Picture was taken during Joint Investigation of 2nd April 2021 .



Close-up: 1.5inch crude oil theft valve installed at 12 o'clock position on 8inch Afam Well 27T  
Flowline at Egberu Picture was taken during Joint Investigation of 2nd April 2021 .