



Overview: Part of spill impact on 20inch Rumuekpe Nkpoku Trunkline at Mbodo Aluu. Picture was taken during Joint Investigation of 19<sup>th</sup> March 2021.



Close-up: 2inch illegal connection installed at 12 o'clock on 20inch Rumuekpe Nkpoku Trunkline at Mbodo Aluu. Picture was taken during Joint Investigation of 19<sup>th</sup> March 2021.