




Overview: Part of spill impact on 16inch Nun-River Kolocreek BVS riser at Agbura-Otuokpoti. Picture was taken during Joint Investigation of 2nd April 2021.



Close-up: Inward dent and Hacksaw cut at 12 o'clock position on 16inch Nun-River Kolocreek BVS riser at Agbura-Otuokpoti. Picture was taken during Joint Investigation of 2nd April 2021.



Close-up: Inward dent and Hacksaw cut at 12 o'clock position on 16inch Nun-River Kolocreek BVS riser at Agbura-Otuokpoti. Picture was taken during Joint Investigation of 2nd April 2021.