



Overview: Part of spill impact on 6inch Seibou Bulkline at Tububou.
Picture was taken during Joint Investigation of 29th June 2021.



Close-up: Hacksaw cut at 3 o'clock position on 6inch Seibou Bulkline at Tububou.
Picture was taken during Joint Investigation of 29th June 2021.