



Overview: Part of spill impact on 12inch ImoRiver 2 – Ogale Pipeline at Owaza. Picture was taken during Joint Investigation of 8th May 2021.



Close-up: Local fabricated clamp fitted with 1 inch ball valve installed at 12 o'clock position on 12inch ImoRiver 2 – Ogale Pipeline at Owaza. Picture was taken during Joint Investigation of 8th May 2021.